

E-tec Interconnect AG

Friedhofstrasse 1
CH-2543 Lengnau
Switzerland

Tel.: +41 32 654 15 50
Fax: +41 32 652 26 93

e-mail: request@e-tec.com
website: www.e-tec.com

**Compliance Certificate REACH
REACH-SVHC Global Statement**

In conformity with the European Regulation 1907/2006 REACH, of the European parliament and the Council of December 18th, 2006 concerning the Registration, Evaluation, Authorisation and Restriction of Chemicals (REACH), E-tec Interconnect AG is be contemplated as a manufacturer of Connectors, Test Sockets and Contacts Terminals used in the electronic industry, and to be considered only as downstream user and is neither a substances or preparation manufacturer, nor a reseller and nor a exporter of any substances that should be considered at risk under the latest edicts.

Update of REACH SVHC from 17th January 2022:

The latest update of European Regulation Document from 1907/2006 REACH states:

2. Any producer or importer of articles shall notify the Agency, in accordance with paragraph 4 of this Article, if a substance meets the criteria in Article 57 and is identified in accordance with Article 59(1) if both the following conditions are met:(a) the substance is present in those articles in quantifies totalling over one tonne per producer or importer per year; (b) the substance is present in those articles above a concentration of 0.1 % weight by weight (w/w).

3. Paragraph 2 shall not apply where the producer or importer can exclude exposure to humans or the environment during normal or reasonably foreseeable conditions of use including disposal. In such cases, the producer or importer shall supply appropriate instructions to the recipient of the article.

Following the last REACH SVHC January 17, 2022 update of the Substance of very high concern list with 223 substances, as published by the European Chemicals Agency [Candidate List of substances of very high concern for Authorisation - ECHA \(europa.eu\)](https://echa.europa.eu/en/candidate-list-table)

We confirm that have not been intentionally added nor believe to be contained in any of the materials used for the production of any E-tec Interconnect AG products listed here down any substance from this list.

E-tec Interconnect AG

Friedhofstrasse 1
CH-2543 Lengnau
Switzerland

Tel.: +41 32 654 15 50
Fax: +41 32 652 26 93

e-mail: request@e-tec.com
website: www.e-tec.com

Product Family:

E-tec Interconnect Product Family	
Board to Board / Wire to Board & Wire to Wire Connectors	
I/O Connectors	
DIP & Rotary Switch	

Products :

Part-Number	Part-Number	Part-Number
BB1 - 4 xx - S43 x - 55/2	CRF - 999/27 - S250 - 99	FCZ - xxx - H080 - 99
BB1 - xxx - B850 - 55	CRF - 999/27 - UT250 - 99	FCZ - xxx - H081 - 99
BB1 - xxx - S50 x - 55	CRF - 999/28 - F254 - 99	FCZ - xxx - H100 - 99/x
BB2 - x xx - S430 - 55/2	CRF - 999/28 - R250 - 99	FCZ - xxx - H101 - 99/x
BB2 - xxx - B850 - 55	CRF - 999/29 - C200 - 99	FCZ - xxx - H102 - 99/x
BB2 - xxx - S500 - 55	CRF - 999/30 - K200 - 99	FCZ - xxx - H103 - 99/x
BE x - xxx - S xxx - 55	CRF - 999/30 - O200 - 99	FCZ - xxx - H115 - 99/x
BE x - xxx - S8 xx - 55/2	CRF - 999/30 - SH200 - 99	FCZ - xxx - H116 - 99/x
BF x - xxx - S500 - 55	CRF - 999/35 - D125 - 95	FCZ - xxx - R100 - 99
BF x - xxx - S680 - 55	CRF - 999/35 - K150 - 99	FCZ - xxx - R101 - 99
BF x - xxx - S710 - 55	CRF - 999/35 - L100 - 99	FCZ - xxx - R125 - 99
BF x - xxx - S850 - 55	CRF - 999/35 - S125 - 99	FCZ - xxx - RL100 - 99
BF1 - xxx - R500 - 55	CRF - 999L/27 - H254 - 95	FCZ - xxx - RL101 - 99
BH x - xxx - R850 - 55	CRF - 999X/32 - H200 - 55	FCZ - xxx - S100 - 99
BH2 - xxx - R345 - 55/11	CRF - 1 xx - C200	FCZ - xxx - S125 - 99
BH2 - xxx - R450 - 55/2	CRR - 1 xx - F254 - 99	FCZ - xxx - SL100 - 99
BL x - xxx - R842 - 55	CRR - 1 xx - I250 - 99	FCZ - xxx - SR100 - 99
BL x - xxx - S400 - 55/2	CRR - 1 xx - K150 - 99	FCZ - xxx - V050 - 99/xx
BL x - xxx - S430 - 55/2	CRR - 1 xx - O200 - 99	FCZ - xxx - VC50 - 99/xx
BL x - xxx - S460 - 55/1	CRR - 1 xx - P200 - 99/P	FCZ - xxx - VC51 - 99/xx
BL x - xxx - S570 - 55	CRR - 1 xx - P250 - 99	FCZ - xxx - V052 - 99/xx
BL x - xxx - S842 - 55	CRR - 1 xx - R250 - 99	FCZ - xxx - V053 - 99/xx
BL x - xxx - S850 - 55/1	CRR - 1 xx - S125 - 99	FCZ - xxx - V100 - 99/xx
BL x - xxx - SH635 - 55/2	CRR - 1 xx - S250 - 99	FCZ - xxx - VZ100 - 99/xx
BL1 - xxx - R430 - 55/2	CRR - 1 xx - SD125 - 99/R	FCZ - xxx - V115 - 99/xx
BL1 - xxx - R570 - 55	CRR - 1 xx - SH200 - 99/X	FPC - xxx - R254 - 99
BL2 - xxx - R430 - 55/11	CRR - 1 xx - SK150 - 99/R	FPC - xxx - S254 - 99
BL2 - xxx - R720 - 55/2	CRR - 1 xx - SK200 - 99/X	IDC - xxx - S100 - N5
BL x - xxx - RH635 - 55/2	CRR - 1 xx - SL100 - 99/R	IDC - xxx - W100 - N5
BL2 - xxx - S340 - 55/11	CRR - 1 xx - SS125 - 99/R	IDD - xxx - L100 - 95
BL2 - xxx - S430 - 55/11	CRR - 1 xx - UT250 - 99	IDD - xxx - LE100 - N5
BL4 - xxx - S630/x - 55/2	CRR - 1 xx - C200 - 99	IDD - xxx - S100 - N5
BS1 - xxx - B21x - 55/11 XX	CRR - 2 xx - SL100 - 99/R	IDD - xxx - SE100 - N5
BS1 - xxx - H43 x - 55/2 X	CRR - 2 xx - D200 - 99	IDF - 1 xx/X - P396 - 99
BS1 - xxx - H45 x - 55/11 XX	CRS - 1 xx - F254 - 99	IDF - 1 xx/X - PC396 - 99
BS1 - xxx - H50 x - 55/X	CRS - 1 xx - I250 - 99	IDH - xxx - E100 - N5
BS1 - xxx - H75 x - 55/X	CRS - 1 xx - K150 - 99	IDH - xxx - ES100 - N5
BS1 - xxx - R390 - 55/X	CRS - 1 xx - O200 - 99	IDH - xxx - W100 - N5
BS1 - xxx - T22 x - 55/11 XX	CRS - 1 xx - P200 - 99/P	IDH - xxx - WS100 - N5
BS1 - xxx - TB22 - 55/2 X	CRS - 1 xx - P250 - 99	IDP - xxx - S100 - N5
BS2 - xxx - H222 - 55/00 X	CRS - 1 xx - R250 - 99	IDP - xxx - S200 - N5
BS2 - xxx - H360 - 55/11 X	CRS - 1 xx - S125 - 99	IDP - xxx - S300 - N5
BS2 - xxx - H36A - 55/11 X	CRS - 1 xx - S250 - 99	IDP - xxx - S600 - N5
BS2 - xxx - H430 - 55/2 X	CRS - 1 xx - SH200 - 99/X	IDP - xxx - T050 - 99
BS2 - xxx - H450 - 55/11 X	CRS - 1 xx - SK150 - 99/B	IDS - xxx - S100 - N5/X
BS2 - xxx - H45A - 55/11 X	CRS - 1 xx - SL100 - 99/B	IDS - xxx - S200 - N5/X
BS2 - xxx - H45B - 55/11 X	CRS - 1 xx - SP250 - 99/X	IDS - xxx - W050 - 55/ X
BS2 - xxx - H45P - 55/11 X	CRS - 1 xx - SS125 - 99/X	IDS - xxx - W100 - N5/X
BS2 - xxx - H500 - 55/X	CRS - 1 xx - UT250 - 99	IDS - xxx - W200 - N5/X
BS2 - xxx - H600 - 55/1 X	CRS - 1 xx - C200 - 99	JPC - 127 - BL - 55
BS2 - xxx - H750 - 55/X	CRS - 1 xx - SC200 - 99/x	JPC - 200 - BL - 55
BS2 - xxx - R345 - 55/11 X	CRS - 2 xx - SL100 - 99/E	JPC - 254 - XX - 55
BS2 - xxx - R390 - 55/X	CRS - 2 xx - D200 - 99	JPC - 508 - BL - 55
BS2 - xxx - R500 - 55/2 X	DHL - xxx - R100 - 55	JPE - 200 - XX - 55
BS2 - xxx - TB22 - 55/11 X	DHL - xxx - S100 - 55	JPE - 254 - XX - 55
BS2 - xxx - TB22 - 55/2 X	DHS - xxx - R100 - 55	JPH - 200 - XX - 55
BS2 - xxx - TB28 - 55/2 X	DHS - xxx - S100 - 55	JPH - 254 - XX - 55
BS2 - xxx - TB365 - 55/X	DHW - xxx - R100 - 55	JPM - xx - 200 - BL - 55
BW2 - xxx - R850 - 55/P	DHW - xxx - S100 - 55	JPM - xx - 254 - BL - 55
BW2 - xxx - S850 - 55/P	ECC - 120 - P050 - 95	JPW - 102 - 55
CRF - 1 xx - D125	ECC - 184 - P053 - 95	JPW - 254 - 55
CRF - 1 xx - F254	ECC - 184 - P055 - 95	JPW - 508 - 55
CRF - 1 xx - H200	ECC - xxx - RC100 - 95	JPW - 762 - 55
CRF - 1 xx - H254	ECC - xxx - S050 - 95/x	MMF - xxx - DC50 - 99
CRF - 1 xx - I250	ECC - xxx - SC100 - 95	MFP - xxx - DC50 - 99
CRF - 1 xx - K150	ECC - xxx/X - R100 - 95	MMF - xxx - RB50 - 99
CRF - 1 xx - K200	ECC - xxx/X - S100 - 95	MMF - xxx - RL50 - 99
CRF - 1 xx - L100	FCA - x xx - X xxx - xxxxxx - x	MMF - xxx - SB50 - 99
CRF - 1 xx - O200	FCL - xxx - H100 - 99/x	MMF - xxx - SL50 - 99
CRF - 1 xx - P200	FCL - xxx - H125 - 99/X	MMF - xxx - HB50 - 99/X
CRF - 1 xx - P250	FCL - xxx - R100 - 99	MMF - xxx - HL50 - 99/X
CRF - 1 xx - R250	FCL - xxx - R125 - 99	MMM - xxx - HS50 - 99/X
CRF - 1 xx - S125	FCL - xxx - S100 - 99	MMM - xxx - SS50 - 99
CRF - 1 xx - S250	FCL - xxx - S125 - 99	PCC - 1 xx - PM635/x
CRF - 1 xx - SH200	FCL - xxx - V100 - 99/xx	PCC - 3 xx - P635/x
CRF - 1 xx - UT250	FCT - x xx - C xxx - xx	PCF - 1 xx - F396
CRF - 2 xx - D200	FCT - x xx - S xxx - xx	PCF - 1 xx - F508
CRF - 2 xx - H200	FCT - x xx - T xxx - xx	PCF - 1 xx - P420
CRF - 2 xx - H254	FCZ - xxx - H050 - 99/x	PCF - 1 xx - P508
CRF - 2 xx - H254/HP	FCZ - xxx - H051 - 99/x	PCF - 1 xx - P635/x
CRF - 2 xx - L100	FCZ - xxx - HC50 - 99/x	PCF - 1 xx - Q396
CRF - 999/27 - DP200 - 99	FCZ - xxx - HC51 - 99/x	PCF - 1 xx - W300
CRF - 999/27 - H254 - N5	FCZ - xxx - H052 - 99/x	PCF - 104 - I508 - 99/X
CRF - 999/27 - I250 - 99	FCZ - xxx - H053 - 99/x	PCF - 2 xx - BSC420 - 99
CRF - 999/27 - P250 - 99	FCZ - xxx - H058 - 99/x	PCF - 2 xx - P420

Part-Number

PCF - 2 xx - W300
 PCF - 3 xx - P635/x
 PCF - 999/20 - F396 - 99
 PCF - 999/20 - F508 - 99
 PCF - 999/xx - P508 - 99
 PCF - 999/xx - P635 - 99
 PCF - 999/xx - Q396 - 99
 PCF - 999/xxX - P420 - 99
 PCF - 999X/xxX - W300 - 99
 PCM - 1 xx - C508
 PCM - 1 xx - P420
 PCM - 1 xx - PN420
 PCM - 1 xx - W300
 PCM - 1 xx - WN300
 PCM - 2 xx - BC420
 PCM - 2 xx - P420
 PCM - 2 xx - PN420
 PCM - 2 xx - W300
 PCM - 2 xx - WN300
 PCM - 999/19 - C508 - 99
 PCM - 999/xx - W300 - 99
 PCM - 999/xxX - P420 - 99
 PCM - 999X/xx - P635 - 99
 PCR - 1 xx - A420 - 99
 PCR - 1 xx - F396 - 99
 PCR - 1 xx - F508 - 99
 PCR - 1 xx - P396 - 99
 PCR - 1 xx - P420 - 99
 PCR - 1 xx - PWF635 - 99
 PCR - 1 xx - PWM635 - 99
 PCR - 1 xx - Q396 - 99
 PCR - 1 xx - SC300 - 99/X
 PCR - 1 xx - SW300 - 99/R
 PCR - 1 xx - W300 - 99
 PCR - 1 xx - W420 - 99
 PCR - 1 xx - WC300 - 99/X
 PCR - 104 - T508 - 99
 PCR - 2 xx - BM420 - 99
 PCR - 2 xx - P420 - 99
 PCR - 2 xx - SC300 - 99/XX
 PCR - 2 xx - SW300 - 99/R
 PCR - 2 xx - W300 - 99
 PCR - 2 xx - W420 - 99
 PCR - 2 xx - BF300 - 99
 PCR - 2 xx - BM300 - 99
 PCS - 1 xx - F396 - 99
 PCS - 1 xx - F508 - 99
 PCS - 1 xx - P396 - 99
 PCS - 1 xx - P420 - 99
 PCS - 1 xx - PF635 - 99
 PCS - 1 xx - PM635 - 99
 PCS - 1 xx - PN420 - 99
 PCS - 1 xx - Q396 - 99

Part-Number

PCS - 1 xx - SC300 - 99/XX
 PCS - 1 xx - SW300 - 99/B
 PCS - 1 xx - W300 - 99
 PCS - 1 xx - WC300 - 99
 PCS - 104 - T508 - 99
 PCS - 2 xx - BF420 - 99
 PCS - 2 xx - BM420 - 99
 PCS - 2 xx - P420 - 99
 PCS - 2 xx - PN420 - 99
 PCS - 2 xx - SC300 - 99/XX
 PCS - 2 xx - SC300 - 99/XX
 PCS - 2 xx - SW300 - 99/B
 PCS - 2 xx - W300 - 99
 PCS - 2 xx - BF300 - 99
 PCS - 2 xx - BM300 - 99
 PCS - 3 xx - PF635 - 99/X
 PCS - 3 xx - PM635 - 99/X
 PLU - 044 - H901 - 99
 SE2 - xxx - R430 - xx /2
 SE2 - xxx - R635 - 55
 SE2 - xxx - S400 - xx /2
 SE2 - xxx - S740 - 55
 SL1 - xxx - B096/xx - xx /2
 SL1 - xxx - Bxxx/x - 55/11
 SL1 - xxx - K106/xx - xx /2
 SL1 - xxx - N088/xx - xx /2
 SL1 - xxx - R xxx/xx - xx
 SL1 - xxx - R071/x - 55/11
 SL1 - xxx - R106/xx - xx /2
 SL1 - xxx - RH xxx/xx - xx
 SL1 - xxx - S xxx/xx - 55/1
 SL1 - xxx - S xxx/xx - xx
 SL1 - xxx - S088/xx - xx /2
 SL1 - xxx - SH xxx/xx - xx
 SL1 - xxx - U xxx/xx - xx
 SL1 - xxx - UH xxx/xx - xx
 SL2 - xxx - B096/xx - xx /2
 SL2 - xxx - K106/xx - xx /2
 SL2 - xxx - N088/xx - xx /2
 SL2 - xxx - R xxx/xx - xx
 SL2 - xxx - R071/x - 55/11
 SL2 - xxx - R106/xx - xx /2
 SL2 - xxx - RH xxx/xx - xx
 SL2 - xxx - S xxx/xx - 55/1
 SL2 - xxx - S xxx/xx - xx
 SL2 - xxx - S088/xx - xx /2
 SL2 - xxx - SH xxx/xx - xx
 SL2 - xxx - Sxxx/x - 55/00
 SL2 - xxx - Sxxx/x - 55/11
 SL2 - xxx - U xxx/xx - xx
 SL2 - xxx - UH xxx/xx - xx
 SL3 - xxx - R xxx/xx - xx
 SL3 - xxx - RH xxx/xx - xx
 SL3 - xxx - S xxx/xx - xx

Part-Number

SL3 - xxx - SH xxx/xx - xx
 SL3 - xxx - U xxx/xx - xx
 SL3 - xxx - UH xxx/xx - xx
 SL4 - xxx - S830/x - 55/2
 SLS - xxx - D xxx - 55
 SLS - xxx - D762/xx - 55/2
 SLS - xxx - H510 - 55/11 X
 SLS - xxx - H562 - 55/2 X
 SLS - xxx - H610 - 55/11 X
 SLS - xxx - H885 - 55/X
 SLS - xxx - HP2x - 55/11 X
 SLS - xxx - P535/x - 55/11
 SLS - xxx - R103 - 55/X
 SLS - xxx - R510 - 55/11
 SLS - xxx - R562 - 55/2
 SLS - xxx - R565/x - 55/11
 SLS - xxx - R920 - 55
 SLS - xxx - S103 - 55/X
 SLS - xxx - S510 - 55/11
 SLS - xxx - S535 - 55/11
 SLS - xxx - S562 - 55/2
 SLS - xxx - S920 - 55
 SP x - xxx - S xxx/xx - xx
 SP x - xxx - SH xxx/xx - xx
 SP1 - xxx - N xxx/xx - 55/2
 SP1 - xxx - S xxx/x - 55/11
 SP1 - xxx - S xxx/xx - 55/1
 SP1 - xxx - S xxx/xx - 55/2
 SP2 - xxx - HX065/x - 55/2 X
 SPx - xxx - H16x/xx - 55 X
 SP2 - xxx - H220/x - 55/1 X
 SP2 - xxx - H51/x - 55/00 X
 SP2 - xxx - H xx/x - 55/11 X
 SP2 - xxx - N xxx/xx - 55/2
 SP2 - xxx - S xxx/x - 55/11
 SP2 - xxx - S xxx/xx - 55/1
 SP2 - xxx - S xxx/xx - 55/2
 SR1 - xxx - H093/x - 55/2 X
 SR1 - xxx - H135/xx - xx X
 SR2 - xxx - H122/x - 55/2 X
 SR2 - xxx - H135/xx - xx X
 SS1 - xxx - H085/x - 55/2 X
 SS1 - xxx - H14 x /xx - 55 X
 SS1 - xxx - H185/x - 55/2 X
 SS1 - xxx - H38 x /x - 55/1 X
 SS1 - xxx - TH14 x /xx - 55 X
 SS2 - xxx - HX064/x - 55/2 X
 SS2 - xxx - H085/x - 55/2 X
 SS2 - xxx - H140/xx - 55 X
 SS2 - xxx - H18/x - 55/00 X
 SS2 - xxx - H380/x - 55/1 X
 SS2 - xxx - H7x/x - 55/11 X
 SS2 - xxx - TH140/xx - 55 X

Part-Number	Part-Number	Part-Number
DVD-2424-NDD9-xx/BS	SDD-0909-x-95-FMN	SDD-2500-2-95-FNJ
DVD-2424-NDD9-xx/BSJ	SDD-0909-x-95-FMNJ	SDD-2500-2-95-MN
DVD-2424-NDD9-xx/WS	SDD-0909-x-95-FMS	SDD-2500-2-95-MNJ
DVD-2424-NDD9-xx/WSJ	SDD-0909-x-95-FMSJ	SDD-2509-2-95-F
DVD-2929-NAD9-xx/BS	SDD-0909-x-95-FMSN	SDD-2509-2-95-FJ
DVD-2929-NAD9-xx/BSJ	SDD-0909-x-95-FMSNJ	SDD-2509-2-95-FM
DVD-2929-NAD9-xx/WS	SDD-0909-x-95-FN	SDD-2509-2-95-FMJ
DVD-2929-NAD9-xx/WSJ	SDD-0909-x-95-FNJ	SDD-2509-2-95-FMN
DVF-024-NDD1-xx/BB	SDD-0909-x-95-FS	SDD-2509-2-95-FMNJ
DVF-024-NDD1-xx/BBJ	SDD-0909-x-95-FSJ	SDD-2509-2-95-FN
DVF-024-NDD1-xx/WB	SDD-0909-x-95-FSN	SDD-2509-2-95-FNJ
DVF-024-NDD1-xx/WBJ	SDD-0909-x-95-FSNJ	SDD-2509-2-95-M
DVF-024-NDD9-xx/BP	SDD-0909-x-95-M	SDD-2509-2-95-MF
DVF-024-NDD9-xx/BPJ	SDD-0909-x-95-MF	SDD-2509-2-95-MFJ
DVF-024-NDD9-xx/WP	SDD-0909-x-95-MFJ	SDD-2509-2-95-MFN
DVF-024-NDD9-xx/WPJ	SDD-0909-x-95-MFN	SDD-2509-2-95-MFNJ
DVF-029-NAD9-xx/BP	SDD-0909-x-95-MFNJ	SDD-2509-2-95-MJ
DVF-029-NAD9-xx/BPJ	SDD-0909-x-95-MFS	SDD-2509-2-95-MN
DVF-029-NAD9-xx/WP	SDD-0909-x-95-MFSJ	SDD-2509-2-95-MNJ
DVF-029-NAD9-xx/WPJ	SDD-0909-x-95-MFSN	SDD-2525-x-95-F
HMR-B19-SSK1-9x/X	SDD-0909-x-95-MFSNJ	SDD-2525-x-95-FJ
HMR-B19-SSL1-9x/X	SDD-0909-x-95-MJ	SDD-2525-x-95-FM
HMR-B19-SSM1-9x/X	SDD-0909-x-95-MN	SDD-2525-x-95-FMJ
HMR-B19-SWK1-9x/X	SDD-0909-x-95-MNJ	SDD-2525-x-95-FMN
HMR-B19-USM1-9x/X	SDD-0909-x-95-MS	SDD-2525-x-95-FMNJ
HSB-xxx-S101-00Z	SDD-0909-x-95-MSJ	SDD-2525-x-95-FMS
HSB-xxx-S101-45Z	SDD-0909-x-95-MSN	SDD-2525-x-95-FMSJ
HSB-xxx-S102-00Z	SDD-0909-x-95-MSNJ	SDD-2525-x-95-FMSN
HSB-xxx-S102-45Z	SDD-0925-x-95-F	SDD-2525-x-95-FMSNJ
HSC-xxx-S101-00Z	SDD-0925-x-95-FJ	SDD-2525-x-95-FN
HSC-xxx-S101-45Z	SDD-0925-x-95-FN	SDD-2525-x-95-FNJ
HSC-xxx-S102-00Z	SDD-0925-x-95-FNJ	SDD-2525-x-95-FS
HSC-xxx-S102-45Z	SDD-09H15-x-95-F	SDD-2525-x-95-FSJ
HSG-xxx-S101-00Z	SDD-09H15-x-95-FJ	SDD-2525-x-95-FSN
HSG-xxx-S101-45Z	SDD-09H15-4-95-FM	SDD-2525-x-95-FSNJ
HSG-xxx-S102-00Z	SDD-09H15-4-95-FMJ	SDD-2525-x-95-M
HSG-xxx-S102-45Z	SDD-09H15-4-95-FMN	SDD-2525-x-95-MF
HSM-xxx-S101-00Z	SDD-09H15-4-95-FMNJ	SDD-2525-x-95-MFJ
HSM-xxx-S101-0RZ	SDD-09H15-x-95-FN	SDD-2525-x-95-MFN
HSM-xxx-S101-90Z	SDD-09H15-x-95-FNJ	SDD-2525-x-95-MFNJ
HSM-xxx-S101-9RZ	SDD-09H15-x-95-MF	SDD-2525-x-95-MFS
HSM-xxx-S102-00Z	SDD-09H15-x-95-MFJ	SDD-2525-x-95-MFSJ
HSM-xxx-S102-0RZ	SDD-09H15-x-95-MFN	SDD-2525-x-95-MFSN
HSM-xxx-S102-90Z	SDD-09H15-x-95-MFNJ	SDD-2525-x-95-MFSNJ
HSM-xxx-S102-9RZ	SDD-1515-x-95-F	SDD-2525-x-95-MJ
IES-B04-RI01-95	SDD-1515-x-95-FJ	SDD-2525-x-95-MN
IES-B04-RIR1-95	SDD-1515-x-95-FM	SDD-2525-x-95-MNJ
IES-B04-SI01-95	SDD-1515-x-95-FMJ	SDD-2525-x-95-MS
IES-B06-RIF1-95	SDD-1515-x-95-FMN	SDD-2525-x-95-MSJ
IES-B06-SIF1-95	SDD-1515-x-95-FMNJ	SDD-2525-x-95-MSN
IES-B06-VIF1-95	SDD-1515-x-95-FMS	SDD-2525-x-95-MSNJ
IES-W06-RIF1-95	SDD-1515-x-95-FMSJ	SDD-2599-2-95-FM
IES-W06-SIF1-95	SDD-1515-x-95-FMSN	SDD-2599-2-95-FMJ
IES-W06-VIF1-95	SDD-1515-x-95-FMSNJ	SDD-2599-2-95-FMN
JLP-440-T106-NN	SDD-1515-x-95-FN	SDD-2599-2-95-FMNJ
JSR-xxx-Txxx-NN	SDD-1515-x-95-FNJ	SDD-259H15-4-95-FMF
MDJ-606-DKxx-95	SDD-1515-x-95-FS	SDD-259H15-4-95-FMFJ
MDJ-606-DSxx-95	SDD-1515-x-95-FSJ	SDD-259H15-4-95-FMFN
MDJ-xxx-RF01-95	SDD-1515-x-95-FSN	SDD-259H15-4-95-FMFNJ
MDJ-xxx-RF22-95	SDD-1515-x-95-FSNJ	SDD-25H15-4-95-F
MDJ-xxx-RKLS/x-95	SDD-1515-x-95-M	SDD-25H15-4-95-FJ
MDJ-xxx-RKLT/x-95	SDD-1515-x-95-MF	SDD-25H15-4-95-FN
MDJ-xxx-RN01-AGZ	SDD-1515-x-95-MFJ	SDD-25H15-4-95-FNJ
MDJ-xxx-RS01-AGZ	SDD-1515-x-95-MFN	SDD-25L15-2-95-F
MDJ-xxx-SN01-AGZ	SDD-1515-x-95-MFNJ	SDD-25L15-2-95-FJ
MDJ-xxx-SS01-AGZ	SDD-1515-x-95-MFS	SDD-25L15-2-95-FN
MDP-xxx-FA01-AGZ	SDD-1515-x-95-MFSJ	SDD-25L15-2-95-FNJ
MDP-xxx-MA01-AGZ	SDD-1515-x-95-MFSN	SDD-3737-x-95-F
MDP-xxx-MQ01-55	SDD-1515-x-95-MFSNJ	SDD-3737-x-95-FJ
SDD-0900-2-95-FN	SDD-1515-x-95-MJ	SDD-3737-x-95-FM
SDD-0900-2-95-FN	SDD-1515-x-95-MN	SDD-3737-x-95-FMJ
SDD-0900-2-95-MN	SDD-1515-x-95-MNJ	SDD-3737-x-95-FMN
SDD-0900-2-95-MNJ	SDD-1515-x-95-MS	SDD-3737-x-95-FMNJ
SDD-0909-x-95-F	SDD-1515-x-95-MSJ	SDD-3737-x-95-FMS
SDD-0909-x-95-FJ	SDD-1515-x-95-MSN	SDD-3737-x-95-FMSJ
SDD-0909-x-95-FM	SDD-1515-x-95-MSNJ	SDD-3737-x-95-FMSN
SDD-0909-x-95-FMJ	SDD-2500-2-95-FN	SDD-3737-x-95-FMSNJ

Part-Number	Part-Number	Part-Number
SDD-3737-x-95-MFS	SDF-025-US91-95/N	SDM-015-N900-95/N
SDD-3737-x-95-MFSJ	SDF-025-US91-95/SN	SDM-xxx-N901-55/HX
SDD-3737-x-95-MFSN	SDF-037-N900-95/C4	SDM-015-N900-95/NJ
SDD-3737-x-95-MFSNJ	SDF-037-N900-95/C4J	SDM-025-N900-95/C4
SDD-3737-x-95-MJ	SDF-037-N900-95/H	SDM-025-N900-95/C4J
SDD-3737-x-95-MN	SDF-037-N900-95/HJ	SDM-025-N900-95/H
SDD-3737-x-95-MNJ	SDF-037-N900-95/N	SDM-025-N900-95/HJ
SDD-3737-x-95-MS	SDF-037-N900-95/NJ	SDM-025-N900-95/N
SDD-3737-x-95-MSJ	SDF-xxx-B111-95/BR	SDM-025-N900-95/NJ
SDD-3737-x-95-MSN	SDF-xxx-B111-95/BRJ	SDM-037-N900-95/C4
SDD-3737-x-95-MSNJ	SDF-xxx-B111-95/FBRx	SDM-037-N900-95/C4J
SDD-H1500-2-95-FN	SDF-xxx-B111-95/FBRxJ	SDM-037-N900-95/H
SDD-H1500-2-95-FNJ	SDF-xxx-B111-95/FBRxJ	SDM-037-N900-95/HJ
SDD-H1509-6-95-F	SDF-xxx-B111-95/FT	SDM-037-N900-95/N
SDD-H1509-6-95-FJ	SDF-xxx-B111-95/FT0	SDM-037-N900-95/NJ
SDD-H1509-6-95-FN	SDF-xxx-B111-95/FTJ	SDM-xxx-B111-95/BR
SDD-H1509-6-95-FNJ	SDF-xxx-B111-95/T	SDM-xxx-B111-95/BRJ
SDD-H1509-7-95-MF	SDF-xxx-B111-95/T0	SDM-xxx-B111-95/FBRx
SDD-H1509-7-95-MFJ	SDF-xxx-B111-95/TJ	SDM-xxx-B111-95/FBRxJ
SDD-H1509-7-95-MFN	SDF-xxx-L900-95/L	SDM-xxx-B111-95/FT
SDD-H1509-7-95-MFNJ	SDF-xxx-L900-95/LJ	SDM-xxx-B111-95/FT0
SDD-H15H15-4-95-F	SDF-xxx-L900-95/P	SDM-xxx-B111-95/FTJ
SDD-H15H15-4-95-FJ	SDF-xxx-L900-95/PJ	SDM-xxx-B111-95/T
SDD-H15H15-x-95-FM	SDF-xxx-M900-55/H	SDM-xxx-B111-95/T0
SDD-H15H15-x-95-FMJ	SDF-xxx-M900-55/HJ	SDM-xxx-B111-95/TJ
SDD-H15H15-x-95-FMN	SDF-xxx-M900-55/N	SDM-xxx-L900-95/L
SDD-H15H15-x-95-FMNJ	SDF-xxx-M900-55/NJ	SDM-xxx-L900-95/LJ
SDD-H15H15-4-95-FN	SDF-xxx-N900-55/A1T	SDM-xxx-L900-95/P
SDD-H15H15-4-95-FNJ	SDF-xxx-N900-55/A1TJ	SDM-xxx-L900-95/PJ
SDD-H26H26-x-95-F	SDF-xxx-N900-55/A2T	SDM-xxx-M900-55/H
SDD-H26H26-x-95-FJ	SDF-xxx-N900-55/A2TJ	SDM-xxx-M900-55/HJ
SDD-H26H26-x-95-FM	SDF-xxx-N901-55/HX	SDM-xxx-M900-55/N
SDD-H26H26-x-95-FMJ	SDF-xxx-P150-95/P	SDM-xxx-M900-55/NJ
SDD-H26H26-x-95-FMN	SDF-xxx-S101-95/T	SDM-xxx-N900-55/A1T
SDD-H26H26-x-95-FMNJ	SDF-xxx-S101-95/T0	SDM-xxx-N900-55/A1TJ
SDD-H26H26-x-95-FN	SDF-xxx-S111-95/BR	SDM-xxx-N900-55/A2T
SDD-H26H26-x-95-FNJ	SDF-xxx-S111-95/BRJ	SDM-xxx-N900-55/A2TJ
SDD-H44H44-x-95-F	SDF-xxx-S111-95/BW	SDM-xxx-P150-95/P
SDD-H44H44-x-95-FJ	SDF-xxx-S111-95/BWJ	SDM-xxx-S101-95/T
SDD-H44H44-x-95-FN	SDF-xxx-S111-95/FBR	SDM-xxx-S101-95/T0
SDD-H44H44-x-95-FNJ	SDF-xxx-S111-95/FBRJ	SDM-xxx-S111-95/BR
SDD-L1525-2-95-F	SDF-xxx-S111-95/FT	SDM-xxx-S111-95/BRJ
SDD-L1525-2-95-FJ	SDF-xxx-S111-95/FT0	SDM-xxx-S111-95/BW
SDD-L1525-2-95-FN	SDF-xxx-S111-95/FTJ	SDM-xxx-S111-95/BWJ
SDD-L1525-2-95-FNJ	SDF-xxx-S111-95/T	SDM-xxx-S111-95/FBR
SDF-009-N900-95/C4	SDF-xxx-S111-95/T0	SDM-xxx-S111-95/FBRJ
SDF-009-N900-95/C4J	SDF-xxx-S111-95/TJ	SDM-xxx-S111-95/FT
SDF-009-N900-95/H	SDF-xxx-T900-55/A1T	SDM-xxx-S111-95/FT0
SDF-009-N900-95/HJ	SDF-xxx-T900-55/A1TJ	SDM-xxx-S111-95/FTJ
SDF-009-N900-95/N	SDF-xxx-T900-55/A2T	SDM-xxx-S111-95/T
SDF-009-N900-95/NJ	SDF-xxx-T900-55/A2TJ	SDM-xxx-S111-95/T0
SDF-009-US91-95/N	SDF-xxx-T970-95/H1N	SDM-xxx-S111-95/TJ
SDF-009-US91-95/SN	SDF-xxx-T970-95/H1NJ	SDM-xxx-T900-55/A1T
SDF-015-N900-95/C4	SDF-xxx-T970-95/H2N	SDM-xxx-T900-55/A1TJ
SDF-015-N900-95/C4J	SDF-xxx-T970-95/H2NJ	SDM-xxx-T900-55/A2T
SDF-015-N900-95/H	SDM-009-N900-95/C4	SDM-xxx-T900-55/A2TJ
SDF-015-N900-95/HJ	SDM-009-N900-95/C4J	SDM-xxx-T970-95/H1N
SDF-015-N900-95/N	SDM-009-N900-95/H	SDM-xxx-T970-95/H1NJ
SDF-015-N900-95/NJ	SDM-009-N900-95/H1N	SDM-xxx-T970-95/H2N
SDF-015-N900-95/YC4	SDM-009-N900-95/H1NJ	SDM-xxx-T970-95/H2NJ
SDF-015-N900-95/YC4J	SDM-009-N900-95/H2N	SDP-2599-2-95-FM
SDF-015-N900-95/YH	SDM-009-N900-95/H2NJ	SDP-2599-2-95-FMJ
SDF-015-N900-95/YHJ	SDM-009-N900-95/HJ	SDP-2599-2-95-FMN
SDF-015-N900-95/YNJ	SDM-009-N900-95/N	SDP-2599-2-95-FMNJ
SDF-015-US91-95/N	SDM-009-N900-95/NJ	SDP-259H15-4-95-FMF
SDF-015-US91-95/SN	SDM-009-N900-95/TC4	SDP-259H15-4-95-FMFJ
SDF-025-N900-95/BC4	SDM-009-N900-95/TC4J	SDP-259H15-4-95-FMFN
SDF-025-N900-95/BC4J	SDM-009-N900-95/THJ	SDP-259H15-4-95-FMFNJ
SDF-025-N900-95/BH	SDM-009-N900-95/TN	SFF-xxx-L900-95/L
SDF-025-N900-95/BHJ	SDM-009-N900-95/TNJ	SFF-xxx-L900-95/LJ
SDF-025-N900-95/BNJ	SDM-009-US91-95/N	SFF-xxx-L900-95/P
SDF-025-N900-95/C4	SDM-009-US91-95/SN	SFF-xxx-L900-95/PJ
SDF-025-N900-95/C4J	SDM-015-N900-95/C4	SFF-xxx-N900-95/H
SDF-025-N900-95/H	SDM-015-N900-95/C4J	SFF-xxx-N900-95/HJ
SDF-025-N900-95/HJ	SDM-015-N900-95/H	SFF-xxx-N900-95/N
SDF-025-N900-95/N	SDM-015-N900-95/HJ	SFF-xxx-N900-95/NJ
SDF-025-N900-95/NJ		

Part-Number	Part-Number	Part-Number
SDM-xxx-T900-55/A2T	SHF-xxx-S111-95/BR	ULS-W04-RAS0-95
SDM-xxx-T900-55/A2TJ	SHF-xxx-S111-95/BRJ	ULS-W04-RBS0-95
SDM-xxx-T970-95/H1N	SHF-xxx-S111-95/BW	ULS-W04-SAS0-95
SDM-xxx-T970-95/H1NJ	SHF-xxx-S111-95/BWJ	UMS-B04-SAS0-95
SDM-xxx-T970-95/H2N	SHF-xxx-S111-95/T	UMS-B04-SBS0-95
SDM-xxx-T970-95/H2NJ	SHF-xxx-S111-95/T0	UMS-B04-SBS2-98
SDP-2599-2-95-FM	SHF-xxx-S111-95/TJ	UMS-B05-SB21-95
SDP-2599-2-95-FMJ	SHM-xxx-B111-55/BR	UNS-B05-SKB21-58/R
SDP-2599-2-95-FMN	SHM-xxx-B111-55/BRJ	UNS-B05-SKB2L-58/R
SDP-2599-2-95-FMNI	SHM-xxx-B111-55/T	UNS-B05-SKB2P-58/R
SDP-259H15-4-95-FMF	SHM-xxx-B111-55/T0	UNS-B05-SWB2W-56/R
SDP-259H15-4-95-FMFJ	SHM-xxx-B111-55/TJ	USC-xxxx-2AMBM-BG/G
SDP-259H15-4-95-FMFN	SHM-xxx-B111-55/FBRx	USC-xxxx-4AMAM-CH/G
SDP-259H15-4-95-FMFNI	SHM-xxx-B111-95/FBRxJ	USC-xxxx-4MBBM-CH/G
SFF-xxx-L900-95/L	SHM-xxx-B111-95/FT	USC-xxxx-4MIM-CH/G
SFF-xxx-L900-95/LJ	SHM-xxx-B111-95/FT0	USC-xxxx-5MBBM-CH/G
SFF-xxx-L900-95/P	SHM-xxx-B111-95/FTJ	USC-xxxx-AMAF-BG/G
SFF-xxx-L900-95/PJ	SHM-xxx-F900-55/FH	USC-xxxx-AMAM-BG/G
SFF-xxx-N900-95/H	SHM-xxx-F900-55/FHJ	USC-xxxx-BMBM-BG/G
SFF-xxx-N900-95/HJ	SHM-xxx-F900-55/FN	USC-xxxx-IM4M-CH/B
SFF-xxx-N900-95/N	SHM-xxx-F900-55/FNI	USC-xxxx-IMIM-CH/G
SFF-xxx-N900-95/NJ	SHM-xxx-F900-55/H	USP-B04-SA01-95
SFM-xxx-L900-95/L	SHM-xxx-F900-55/HJ	USP-B04-SA11-95
SFM-xxx-L900-95/LJ	SHM-xxx-F900-55/N	USP-B04-SA21-95
SFM-xxx-L900-95/P	SHM-xxx-F900-55/NJ	USP-B04-SA31-95
SFM-xxx-L900-95/PJ	SHM-xxx-S101-95/T	USS-B04-RA01-95
SFM-xxx-N900-95/H	SHM-xxx-S101-95/T0	USS-B04-RA02-95
SFM-xxx-N900-95/HJ	SHM-xxx-S111-95/BR	USS-B04-RB01-95
SFM-xxx-N900-95/N	SHM-xxx-S111-95/BRJ	USS-B04-SA01-95
SFM-xxx-N900-95/NJ	SHM-xxx-S111-95/BW	USS-B04-SB01-95
SHF-015-F900-95/VN	SHM-xxx-S111-95/BWJ	USS-B04-SBS0-95
SHF-015-F900-95/VNI	SHM-xxx-S111-95/T	USS-B04-TA01-95
SHF-015-US98-95/SN	SHM-xxx-S111-95/T0	USS-B04-TB01-95
SHF-xxx-B111-95/BR	SHM-xxx-S111-95/TJ	USS-B04-UB01-95
SHF-xxx-B111-95/BRJ	SKF-xxx-S201-95/T	USS-B04-VA01-95
SHF-xxx-B111-95/FBRx	SKF-xxx-S201-95/T0	USS-B08-TA02-95
SHF-xxx-B111-95/FT	SKF-xxx-S202-95/T	USS-B12-RA03-95
SHF-xxx-B111-95/FT0	SKF-xxx-S202-95/T0	USS-BU09-RA31-98
SHF-xxx-B111-95/FTJ	SKM-xxx-S201-95/T	USS-BU09-RAS31-98
SHF-xxx-B111-95/T	SKM-xxx-S201-95/T0	USS-BU18-RA32-98
SHF-xxx-B111-95/T0	SKM-xxx-S202-95/T	USS-W04-RA01-95
SHF-xxx-B111-95/TJ	SKM-xxx-S202-95/T0	USS-W04-RA02-95
SHF-xxx-F900-55/FH	SLO-xxx-T106-NN	USS-W04-RB01-95
SHF-xxx-F900-55/FHJ	SSF-015-HU98-95/N	USS-W04-SAS0-95
SHF-xxx-F900-55/FN	SSF-015-HU98-95/R	USS-W04-SB01-95
SHF-xxx-F900-55/FNI	SSF-xxx-U908-95/N	USS-W04-SBS0-95
SHF-xxx-F900-55/H	SSF-xxx-U908-95/R	USS-W04-TA01-95
SHF-xxx-F900-55/HJ	SSM-xxx-U908-95/N	USS-W04-TB01-95
SHF-xxx-F900-55/N	SSM-xxx-U908-95/R	USS-W04-UB01-95
SHF-xxx-F900-55/NJ	ULS-B04-RAS0-95	USS-W04-VA01-95
SHF-xxx-S101-95/T	ULS-B04-RBS0-95	USS-W08-TA02-95
SHF-xxx-S101-95/T0	ULS-B04-SAS0-95	USS-W12-RA03-95
	ULS-BU09-SAS31-98	

Part-Number

DM1-100-VCA9-95/1L
DM1-168-RCA9-95/1L
DM1-168-SXA8-95/1L
DM1-168-VXX9-95/1L
DR1-184-VBZ9-95/1L
HCP-xxx
LCC-xxx-Hxxx-xx
LOC-xxx-T051-99
PLE-xxx-N115-xx
PLP-xxx-H100-99/x
PLP-xxx-N110-99
PLS-xxx-H105-99/x
PUL-xxx
PUS-xxx
SM1-xxx-TS99-99/1x
SM1-xxx-TV99-99/1x

Part-Number

DAH-1xx-E01Z
DAH-1xx-EZ
DAH-1xx-L01Z
DAH-1xx-LT01Z
DAH-1xx-LTZ
DAH-1xx-LZ
DAM-1xx-E01Z
DAM-1xx-EZ
DAM-1xx-L01Z
DAM-1xx-LT01Z
DAM-1xx-LTZ
DAM-1xx-LZ
DDG-1xx-LTZ
DDG-1xx-LZ
DDG-1xx-SRAZ
DDG-1xx-STZ
DDG-1xx-SZ
DDG-2xx-STZ
DDG-2xx-SZ
DDG-3xx-STZ
DDG-3xx-SZ
DDG-4xx-LTZ
DDG-4xx-LZ
DDG-4xx-SRAZ
DDG-4xx-STZ
DDG-4xx-SZ
DDG-5xx-LTZ
DDG-5xx-LZ
DDG-5xx-SRAZ
DDG-5xx-STZ
DDG-5xx-SZ
DDG-6xx-STZ
DDG-6xx-SZ
DDS-1xx-LTZ
DDS-1xx-LZ
DDS-1xx-SRAZ
DDS-1xx-STZ
DDS-1xx-SZ
DDS-2xx-STZ
DDS-2xx-SZ
DDS-3xx-STZ
DDS-3xx-SZ
DDS-4xx-LTZ
DDS-4xx-LZ
DDS-4xx-SRAZ
DDS-4xx-STZ
DDS-4xx-SZ
DDS-5xx-LTZ
DDS-5xx-LZ

Part-Number

DDS-5xx-SRAZ
DDS-5xx-STZ
DDS-5xx-SZ
DDS-6xx-STZ
DDS-6xx-SZ
DHS-1xx-LCZ
DHS-1xx-LDZ
DHS-1xx-LTZ
DHS-1xx-LZ
DPA-1xx-EA00Z
DPA-1xx-EA10Z
DPA-1xx-LA00Z
DPA-1xx-LA10Z
DPA-1xx-LAT0Z
DPA-1xx-LAT1Z
DPG-1xx-ATZ
DPG-1xx-AZ
DPG-1xx-BTZ
DPG-1xx-BZ
DPG-2xx-ATZ
DPG-2xx-AZ
DPG-2xx-BTZ
DPG-2xx-BZ
DPG-3xx-ATZ
DPG-3xx-AZ
DPG-3xx-BTZ
DPG-3xx-BZ
DPG-4xx-ATZ
DPG-4xx-AZ
DPG-4xx-BTZ
DPG-4xx-BZ
DPG-5xx-ATZ
DPG-5xx-AZ
DPG-5xx-BTZ
DPG-5xx-BZ
DPG-6xx-ATZ
DPG-6xx-AZ
DPG-6xx-BTZ
DPG-6xx-BZ
DPH-1xx-EAZ
DPH-1xx-LATZ
DPH-1xx-LAZ
DPI-1xx-EA10Z
DPI-1xx-EB10Z
DPI-1xx-LA10Z
DPI-1xx-LB10Z
DPM-1xx-EA10Z
DPM-1xx-EA11Z
DPM-1xx-EB10Z

Part-Number

DPM-1xx-EB11Z
DPM-1xx-LA10Z
DPM-1xx-LA11Z
DPM-1xx-LAT0Z
DPM-1xx-LAT1Z
DPM-1xx-LB10Z
DPM-1xx-LB11Z
DPM-1xx-LBT0Z
DPM-1xx-LBT1Z
DPS-1xx-ATZ
DPS-1xx-AZ
DPS-1xx-BTZ
DPS-1xx-BZ
DPS-2xx-ATZ
DPS-2xx-AZ
DPS-2xx-BTZ
DPS-2xx-BZ
DPS-3xx-ATZ
DPS-3xx-AZ
DPS-3xx-BTZ
DPS-3xx-BZ
DPS-4xx-ATZ
DPS-4xx-AZ
DPS-4xx-BTZ
DPS-4xx-BZ
DPS-5xx-ATZ
DPS-5xx-AZ
DPS-5xx-BTZ
DPS-5xx-BZ
DPS-6xx-ATZ
DPS-6xx-AZ
DPS-6xx-BTZ
DPS-6xx-BZ
DRD-1xx-CFZ
DRD-1xx-CMZ
DRD-1xx-CRZ
DRD-1xx-CSZ
DRD-1xx-RFZ
DRD-1xx-RMZ
DRD-1xx-RRZ
DRD-1xx-RSZ
DRD-2xx-CFZ
DRD-2xx-CRZ
DRD-2xx-CSZ
DRD-2xx-RFZ
DRD-2xx-RRZ
DRD-2xx-RSZ
DRD-4xx-CFZ
DRD-4xx-CMZ

Part-Number

DRD-4xx-CRZ
DRD-4xx-CSZ
DRD-4xx-RFZ
DRD-4xx-RMZ
DRD-4xx-RRZ
DRD-4xx-RSZ
DRD-5xx-CFZ
DRD-5xx-CRZ
DRD-5xx-CSZ
DRD-5xx-RFZ
DRD-5xx-RRZ
DRD-5xx-RSZ
DSD-1xx-EZ
DSD-1xx-LCZ
DSD-1xx-LDZ
DSD-1xx-LTZ
DSD-1xx-LZ
DSL-1xx-EZ
DSL-1xx-LCZ
DSL-1xx-LDZ
DSL-1xx-LTZ
DSL-1xx-LZ
DSP-42-E01Z
DSP-42-E02Z
DSP-42-EC02Z
DSP-42-L01Z
DSP-42-L02Z
DSP-42-LC02Z
DSP-42-LD02Z
DSP-42-LT01Z
DSP-42-LT02Z
DSS-1010Z
DSS-2010Z
DSS-3020Z
DSS-4020KDZ
DSS-4020Z
DTA-1xx-ETZ
DTA-1xx-EZ
DTA-1xx-LTZ
DTA-1xx-LZ
DTD-1xx-ETZ
DTD-1xx-EZ
DTS-1xx-ETZ
DTS-1xx-EZ
DTS-1xx-LTZ
DTS-1xx-LZ

E-tec Interconnect AG

Friedhofstrasse 1
CH-2543 Lengnau
Switzerland

Tel.: +41 32 654 15 50
Fax: +41 32 652 26 93

e-mail: request@e-tec.com
website: www.e-tec.com

This letter is to confirm that the product(s) referenced above have been evaluated against Regulation (EC) 1907/2006 of the European Parliament, "**Registration, Evaluation, and Authorization of Chemicals (REACH)**", as interpreted by EU Court of Justice decision C-106/14 of 10 September 2015. The compliance status of the product is confirmed by the sections below.

EU Regulation 1907/2006 (select one):

- ☒ The product(s) referenced above, as well as any articles* contained within the product(s), **DO NOT CONTAIN** any of the 223 REACH SVHCs as updated by ECHA on January 17, 2022 (<http://echa.europa.eu/candidate-list-table>).
- ☐ The products(s) referenced above have been evaluated for the presence of the 223 REACH SVHCs as updated BY ECHA on Jan. 17, 2022. The product(s) and/or articles* contained within the product(s) **CONTAIN** the following SVHCs in amounts no more than 1000ppm, as provided in the table on the following page. *(Table must be completed if this option is selected.)*
- ☐ The products(s) referenced above have been evaluated for the presence of the 223 REACH SVHCs as updated BY ECHA on Jan. 17, 2022. The product(s) and/or articles* contained within the product(s) **CONTAIN** the following SVHCs in amounts **more than 1000ppm**, as provided in the table on the following page. *(Table must be completed if this option is selected.)*

*An Article is any item within a part or component of the product which during production is given a special shape, surface or design that determines its function to a greater degree than its chemical composition. An example of articles within an electronic component would be the leads of a through-hole capacitor. For more information, please refer to Example 21 of the EU Chemicals Agency "Guidance for Requirements on Substances in Articles"

(https://echa.europa.eu/documents/10162/23036412/articles_en.pdf/cc2e3f93-8391-4944-88e4-efed5fb5112c)

The latest 223 substances subject to analysis per the REACH Regulation were **last updated on Jan. 17, 2022**. Please refer to the following for the most current candidate list of substances:
<http://echa.europa.eu/candidate-list-table>.

Additional information on the European Union's REACH regulation can be found here:
<https://echa.europa.eu/regulations/reach/understanding-reach>

Authorized Signature:

A handwritten signature in blue ink, appearing to read "P. Rodriguez", is written over a horizontal line.

Name : Pablo Rodriguez

Title : CEO

Date : 20th January 2022